Dart Aerospace Ltd. Monday, 17/07/2006 2:57:45 PM Date Linda Lacelle User **Process Sheet** : BASKET HINGE **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 27868 : 10903 **Estimate Number** : D33281 : NIA **Part Number** P.O. Number . D3328 REV B S.O. No. : 1) A **Drawing Number** : 17/07/2006 This Issue : N/A Project Number : NC Prsht Rev. ; B : PURCHASED PARTS **Drawing Revision** : 17/07/2006 Type First Issue : NIA **Material** : 27868 **Previous Run** : 24/07/2006 Qty: 12 Um: Each **Due Date** Written By Checked & Approved By A 05.02.09 New issue KJ/JLM : Est. Comment waterjet EC Est: rev B 06.07.17 **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** 1010-1025 sheet .125 1.0 M1010S125 0.3024 sf(s)Comment: Qtv.: 0.0252 sf(s)/Unit Total: 1010-1025 sheet .125 batch:<u>M15975</u> FLOW WATER JET 2.0 WATER JET Comment: FLOW WATER JET 1-Cut as per Dwg D3328 Dwg Rev: 13 Prog Rev: 2-Deburr if necessary 3.0 QC2 Comment: INSPECT PARTS AS THEY COME OFF MACHINE SECOND CHECK 4.0 Comment: SECOND CHECK SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 5.0 Comment: SMALL & MEDIUM FAB RESOURCE 1

· Deburr

Date: User:

Monday, 17/07/2006 2:57:45 PM

Linda Lacelle

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BASKET HINGE

Job Number: 27868

Part Number: D33281

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock Location: 64

U

7.0

DC

DOCUMENT CONTROL





Comment: DOCUMENT CONTROL Inspection Level 21

Job Completion



Qty:

12 Um:

Each

: BASKET HINGE

: D33281

: 7/18/2006

: N/A

: B

. D3328 REV B

Tuesday, 7/11/2006 1:05:50 PM

User:

Kim Johnston

## **Process Sheet**

**Drawing Name** 

**Part Number** 

Material

**Due Date** 

**Drawing Number** 

**Project Number** 

**Drawing Revision** 

Customer

Written By

Comment

: CU-DAR001 Dart Helicopters Services

**Job Number** 

: 27868

**Estimate Number** 

: 10903

P.O. Number

This Issue

: 7/11/2006

: NC Prsht Rev. : //

First Issue **Previous Run** 

Checked & Approved By

S.O. No. .:

Type

: PURCHASED PARTS

New issue KJ/JLM : Est.

**Additional Product** 

Job Number:




Seq. #:

Machine Or Operation:

Description: PURCHASING

1.0



Issue P/O: Email or Ship DXF file to vendor

Laser Cut flat pattern per Dwg D3328 Possible Supplier: Industrial Laser Material release note is required

2.0 D33281F Basket Hinge





Comment: Qty.: 1.0000 U(s)/Unit Total:

12.0000 U(s)



PACKAGING 1 3.0

PACKAGING RESOURCE #



Comment: PACKAGING RESOURCE #1

Recieive & Inspect for Transit Damage Ensure Material Release Note is attached

4.0

QC6

DIMENSIONAL CHECK



Comment: DIMENSIONAL CHECK

5.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr





Page 1

## **Dart Aerospace Ltd**

W/O:			WO	RK ORDER CHANGES	3				<u>,                                      </u>
DATE	STEP	STEP PRO		CEDURE CHANGE		Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
ţ									
NCR:		V	VORK ORDE	R NON-CONFORMAN	CE (NCR	)			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section B Action Description	Sign &		Verification Section C	Approval Design Mgr	Approval QC Inspector
			Design Mgr	Design Mgr	Date				20050010
	-			·					
							,		
Part No	):	PAR #:	Fault Category	: NCR:	Yes No	DQA:		Date:	
NOTE: D	ate & initial a	•			QA: N/C CI	osed:			

Date: Tuesday, 7/11/2006 1:05:51 PM

ปรer: Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BASKET HINGE

Job Number: 27868

Part Number: D33281

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

6.0

7.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

DC

DOCUMENT CONTROL





Comment: DOCUMENT CONTROL


Inspection Level 21

Job Completion



## **Dart Aerospace Ltd**

W/O:			WO	RK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
		· .							
				,					
							ŀ		
NCR:		We	ORK ORDE	R NON-CONFORMANC	E (NCF	R)			
DATE	STEP	Description of NC	Corrective Action Section B			Verifi	erification	Approval	Approva
DATE		Section A	Initial Design Mgr	Action Description  Design Mgr	Sign 8 Date		Section C	Design Mgr	QC Inspector
									,
									r
Part No	):	PAR #: F	ault Category	:NCR: Ye	es No	DQA·		Date:	
		al all entries			A: N/C CI			Date:	



DART AEROSPACE LTD	Work Order: 27868
п	2200.1
Description:	Part Number: \$\D332\%\
Inspection Dwg: Rev: 35	Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
1.875	H- D.010	1.878	1		vern	
1.750	+1-0.010	1.753	V		Yean	•
0.625	+1-0.010	.635	1		Hight Gorac	e
RO.125	+1-0.010	RO. 125	<b>√</b>		Hight Gunc Radius gons	<u> </u>
Ø 0.257	t/-0.005,0.00	0.057	<b>V</b>		vern	
· · · · · · · · · · · · · · · · · · ·				<u>  .                                   </u>		

	1 /			
Measured by:	W. M	Audited by:	Prototype Approval:	N/2
Date:	, ,	) Date: (6.07.20	Date:	

Rev	Date	Change	Revised by	Approved
A			KJ/JLM	

